




GNAV Toggle Arrangement

595-487-E
Date: 050305



It is vital that the GNAV toggle is assembled as shown above.
Failure to do this will result in damage to the Strut Assembly